

**Flood Control Project Maintenance  
Levee Inspections**  
**LMA District Cover Sheet**  
**Spring 2008 Levee Inspection Results**

**Merced County Stream Group**

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)				

\*\* Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

\* **SPRING INSPECTIONS:** Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

**FALL INSPECTIONS:** The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports.

Comments


**Flood Control Project Maintenance  
Levee Inspections  
Unit Cover Sheet  
Spring 2008 Levee Inspection Results  
Merced County Stream Group**

Waterway		Bank	Unit Miles
Unit No. 01 Black Rascal Diversion		Right	1.60

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection	3/3/2008			
DWR Inspector	Herman Phillips			
Accompanied By				
Unit Maintenance Rating (Fall Only)				

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Room LL-30  
Sacramento, CA 95821-9000.


**X** \_\_\_\_\_  
Signature of LMA Representative Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2008**

**Merced County Stream Group**

Waterway				Bank	Unit Miles	Inspection Date	Inspector
Unit No. 01 Black Rascal Diversion				Right	1.60	03/03/2008	Herman Phillips

  

LMR Line	Levee Mile		Category	Item	Location*	Rating**	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.50	0.50	Earthen Levee	Crown Surface / Depressions / Rutting	WS	M	Add appropriate gravel or road base. Grade and compact.	37.321775 ° -120.396422 °	37.321825 ° -120.396457 °		1
2	0.91	0.92	Earthen Levee	Encroachments	WS	Fences		37.327642 ° -120.396333 °	37.327773 ° -120.396532 °		2

<p><b>* Location</b></p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p><b>** Rating</b></p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> <p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---

**Flood Control Project Maintenance  
Levee Inspections  
Unit Cover Sheet  
Spring 2008 Levee Inspection Results  
Merced County Stream Group**

Waterway		Bank	Unit Miles
Unit No. 02 Black Rascal Diversion		Left	1.90

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection	3/3/2008			
DWR Inspector	Herman Phillips			
Accompanied By				
Unit Maintenance Rating (Fall Only)				

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :  
 DWR Summer/Winter Inspection Reports  
 3310 El Camino Avenue, Room LL-30  
 Sacramento, CA 95821-9000.


**X** \_\_\_\_\_  
 Signature of LMA Representative Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2008**

**Merced County Stream Group**

Waterway				Bank	Unit Miles	Inspection Date	Inspector
Unit No. 02 Black Rascal Diversion				Left	1.90	03/03/2008	Herman Phillips

LMR Line	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.00	0.00	Earthen Levee	Encroachments	CR	M	Fences	°	°		2
2	0.00	0.00	Earthen Levee	Animal Control	LS	M	Exterminate rodents and backfill and compact or grout burrows.	°	°		3
3	0.00	0.62	Earthen Levee	Crown Surface / Depressions / Rutting	CR	M	Keep the crown roadway free of vegetation.	37.337078 ° -120.387297 °	37.332183 ° -120.394058 °		1
4	0.27	1.69	Earthen Levee	Crown Surface / Depressions / Rutting	CR	M	Keep the crown roadway free of vegetation.	37.318225 ° -120.397097 °	37.317333 ° -120.394985 °		7
5	0.95	0.95	Earthen Levee	Encroachments	CR	PO	Fences	37.327908 ° -120.396068 °	37.327908 ° -120.396068 °		5
6	1.30	1.64	Earthen Levee	Crown Surface / Depressions / Rutting	CR	M	Regrade the crown roadway for proper drainage.	37.322797 ° -120.396028 °	37.318058 ° -120.395742 °		6
7	1.69	1.69	Earthen Levee	Animal Control	LS	M	Exterminate rodents and backfill and compact or grout burrows.	37.317333 ° -120.394985 °	37.317333 ° -120.394985 °		4

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected
--	--

**Flood Control Project Maintenance  
Levee Inspections  
Unit Cover Sheet  
Spring 2008 Levee Inspection Results  
Merced County Stream Group**

Waterway		Bank	Unit Miles
Unit No. 03 Owens Creek Diversion		Right	1.40

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection	3/4/2008			
DWR Inspector	Herman Phillips			
Accompanied By				
Unit Maintenance Rating (Fall Only)				

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Room LL-30  
Sacramento, CA 95821-9000.


**X** \_\_\_\_\_  
Signature of LMA Representative Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2008**

**Merced County Stream Group**

Waterway					Bank	Unit Miles	Inspection Date	Inspector			
Unit No. 03 Owens Creek Diversion					Right	1.40	03/04/2008	Herman Phillips			
LMR Line	Levee Mile		Category	Item	Location*	Rating**	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.00	0.34	Earthen Levee	Vegetation	CR	M	Control annual grass and weeds on the levee slopes and easements.	37.292232 ° -120.321020 °	37.262370 ° -120.288442 °		1
2	0.00	0.34	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	37.292232 ° -120.321020 °	37.262367 ° -120.288440 °		2
3	0.39	0.60	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	37.263095 ° -120.288262 °	37.266075 ° -120.288177 °		5
4	0.39	0.63	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	37.263093 ° -120.288258 °	37.266345 ° -120.287932 °		4
5	0.39	1.25	Earthen Levee	Vegetation	CR	M	Control annual grass and weeds on the levee slopes and easements.	37.263093 ° -120.288258 °	37.272560 ° -120.280452 °		3
6	0.70	1.44	Earthen Levee	Animal Control	WS	M	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows.	37.267302 ° -120.287190 °	37.273742 ° -120.277737 °		6
7	1.19	1.27	Earthen Levee	Animal Control	LS	M	Exterminate rodents and backfill and compact or grout burrows.	37.272388 ° -120.281348 °	37.272840 ° -120.280295 °		7
8	1.24	1.25	Earthen Levee	Animal Control	CR	U	Exterminate rodents and backfill and compact or grout burrows.	37.272537 ° -120.280500 °	37.272560 ° -120.280447 °		8
9	1.28	1.44	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	37.273070 ° -120.280252 °	37.273737 ° -120.277730 °		9
10	1.28	1.44	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	37.273072 ° -120.280255 °	37.273735 ° -120.277725 °		10
11	1.34	1.44	Earthen Levee	Crown Surface / Depressions / Rutting	CR	M	Regrade the crown roadway for proper drainage.	37.273503 ° -120.279457 °	37.273742 ° -120.277733 °		11

<p><b>* Location</b></p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p><b>** Rating</b></p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> <p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---

**Flood Control Project Maintenance  
Levee Inspections  
Unit Cover Sheet  
Spring 2008 Levee Inspection Results  
Merced County Stream Group**

Waterway		Bank	Unit Miles
Unit No. 04 Owens Creek Diversion		Left	1.40

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection	3/4/2008			
DWR Inspector	Herman Phillips			
Accompanied By				
Unit Maintenance Rating (Fall Only)				

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Room LL-30  
Sacramento, CA 95821-9000.


**X** \_\_\_\_\_  
Signature of LMA Representative Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2008**

**Merced County Stream Group**

Waterway				Bank	Unit Miles	Inspection Date	Inspector
Unit No. 04 Owens Creek Diversion				Left	1.40	03/04/2008	Herman Phillips

LMR Line	Levee Mile		Category	Item	Location*	Rating**	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.13	1.03	Earthen Levee	Animal Control	WS	U	Exterminate rodents and backfill and compact or grout burrows.	37.272967 ° -120.280057 °	37.262877 ° -120.287860 °		2
2	0.13	1.03	Earthen Levee	Animal Control	LS	U	Exterminate rodents and backfill and compact or grout burrows.	37.272967 ° -120.280055 °	37.262870 ° -120.287862 °		1
3	0.13	1.03	Earthen Levee	Vegetation	CR	M	Control annual grass and weeds on the levee slopes and easements.	37.272965 ° -120.280060 °	37.262883 ° -120.287858 °		3
4	0.20	0.28	Earthen Levee	Erosion / Bank Caving	WS	M	Note and monitor erosion site.	37.272313 ° -120.280768 °	37.271775 ° -120.281965 °		4
5	0.35	1.41	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	37.262395 ° -120.288258 °	37.257503 ° -120.288102 °		8
6	0.35	1.41	Earthen Levee	Crown Surface / Depressions / Rutting	CR	M	Keep the crown roadway free of vegetation.	37.262395 ° -120.288260 °	37.257503 ° -120.288102 °		9
7	0.35	1.41	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	37.262397 ° -120.288260 °	37.257505 ° -120.288102 °		7
8	0.42	0.45	Earthen Levee	Erosion / Bank Caving	WS	U	Note and monitor erosion site.	37.270597 ° -120.284062 °	37.270293 ° -120.284283 °		5
9	0.61	0.63	Earthen Levee	Animal Control	CR	U	Exterminate rodents and backfill and compact or grout burrows.	37.268428 ° -120.285887 °	37.268142 ° -120.286112 °		6
10	1.16	1.41	Earthen Levee	Animal Control	WS	U	Exterminate rodents and backfill and compact or grout burrows.	37.261007 ° -120.288170 °	37.257498 ° -120.288100 °		11
11	1.16	1.41	Earthen Levee	Animal Control	LS	U	Exterminate rodents and backfill and compact or grout burrows.	37.261005 ° -120.288168 °	37.257502 ° -120.288102 °		10

<p><b>* Location</b></p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p><b>** Rating</b></p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p> <p>PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected</p>
---	---